


Copyright © 2015 Kimley-Horn and Associates, Inc.

All rights reserved





BM#1 TXDOT CONTROL POINT NO. E0430313 BEING A 2-INCH ALUMINUM DISK STAMPED "TXDOT DALLAS GPS E0430313" FOUND IN CONCRETE, ±51 FEET WEST OF STATE HIGHWAY 5 AT FANNIN

ELEV=661.43

BM#2 TXDOT CONTROL POINT NO. E0430261 BEING A 4-INCH ALUMINUM DISK FOUND IN THE GRASS ±54 FEET NORTH FROM NORTHEAST CORNER OF BIBLE CHURCH SIGN, ±73 FEET SOUTHEAST FROM TELEPHONE PEDESTAL, ±90.5 FEET SOUTH FROM CR 377/1375 SIGN AND ±241 FEET NORTH FROM THE CENTER OF COUNTY ROAD

ELEV=762.64

BM#3 SQUARE CUT WITH "X" CUT SET ON NORTHEAST CORNER OF CONCRETE HEADWALL LOCATED ±13 FEET WEST OF GREENVILLE DRIVE AND ±1290 FEET NORTH OF STACY ROAD. ELEV=644.21

BM#4 BENCH TIE NAIL SET IN NORTH SIDE OF POWER POLE LOCATED ±16 FEET WEST OF GREENVILLE DRIVE AND ±54 FEET NORTH OF

ELEV=673.51

NORTH SIDE OF FRISCO ROAD, ±430 FEET WEST OF THE INTERSECTION OF FRISCO ROAD AND GREENVILLE DRIVE, ±755 FEET EAST OF INTERSECTION OF FRISCO ROAD AND MEDICAL

ELEV=632.28

BM#6 SQUARE CUT ON BACK OF CURB INLET ON THE SOUTHEAST SIDE OF CENTRAL EXPRESSWAY, ±75 FEET NORTHEAST OF THE INTERSECTION OF CENTRAL EXPRESSWAY AND FRISCO ROAD.

BM#7 SQUARE CUT ON SOUTH CORNER OF CURB INLET ON THE SOUTHEAST SIDE OF FAIRVIEW PARKWAY, ±320 FEET SOUTHWEST FROM THE INTERSECTION OF FAIRVIEW PARKWAY AND

ELEV=642.22

All bearings shown are based on grid north of the Texas Coordinate System of 1983, North Central Zone (4202), North American Datum of 1983. All dimensions shown are ground distances.

The property is shown on Map No. 48085C0270J, Community Panel No. 481069 0270 J, dated June 2, 2009 of the National Flood Insurance Program Map, Flood Insurance Rate Map of Collin County, Texas, Federal Emergency Management Agency, Federal Insurance Administration.


The surveyor did not abstract the surveyed property. This survey was performed without the benefit of a current


TOPOGRAPHIC SURVEY PROPOSED FAIRVIEW PARKWAY SOUTH CITY OF FAIRVIEW, COLLIN COUNTY, TEXAS




Dallas, Texas 75251 Fax No. (972) 239-3820 FIRM # 10115500

Drawn by Checked by Project No. CJG/JAD OCT. 2015 061182003







BENCH MARK LIST

BM#1 TXDOT CONTROL POINT NO. E0430313 BEING A 2-INCH ALUMINUM DISK STAMPED "TXDOT DALLAS GPS E0430313" FOUND IN CONCRETE, ±51 FEET WEST OF STATE HIGHWAY 5 AT FANNIN

ELEV=661.43

BM#2 TXDOT CONTROL POINT NO. E0430261 BEING A 4-INCH ALUMINUM DISK FOUND IN THE GRASS ±54 FEET NORTH FROM NORTHEAST CORNER OF BIBLE CHURCH SIGN, ±73 FEET SOUTHEAST FROM TELEPHONE PEDESTAL, ±90.5 FEET SOUTH FROM CR 377/1375 SIGN AND ±241 FEET NORTH FROM THE CENTER OF COUNTY ROAD

ELEV=762.64

BM#3 SQUARE CUT WITH "X" CUT SET ON NORTHEAST CORNER OF CONCRETE HEADWALL LOCATED ±13 FEET WEST OF GREENVILLE DRIVE AND ±1290 FEET NORTH OF STACY ROAD. ELEV=644.21

BM#4 BENCH TIE NAIL SET IN NORTH SIDE OF POWER POLE LOCATED ±16 FEET WEST OF GREENVILLE DRIVE AND ±54 FEET NORTH OF STACY ROAD.

ELEV=673.51

BM#5 SQUARE CUT ON NORTHEAST CORNER OF CURB INLET ON THE NORTH SIDE OF FRISCO ROAD, ±430 FEET WEST OF THE INTERSECTION OF FRISCO ROAD AND GREENVILLE DRIVE, ±755 FEET EAST OF INTERSECTION OF FRISCO ROAD AND MEDICAL CENTER DRIVE.

BM#6 SQUARE CUT ON BACK OF CURB INLET ON THE SOUTHEAST SIDE OF CENTRAL EXPRESSWAY, ±75 FEET NORTHEAST OF THE INTERSECTION OF CENTRAL EXPRESSWAY AND FRISCO ROAD. ELEV=660.64

BM#7 SQUARE CUT ON SOUTH CORNER OF CURB INLET ON THE SOUTHEAST SIDE OF FAIRVIEW PARKWAY, ±320 FEET SOUTHWEST FROM THE INTERSECTION OF FAIRVIEW PARKWAY AND RIDGEVIEW DRIVE.

ELEV=642.22

NOTES:

All bearings shown are based on grid north of the Texas Coordinate System of 1983, North Central Zone (4202), North American Datum of 1983. All dimensions shown are ground distances.

The property is shown on Map No. 48085C0270J, Community Panel No. 481069 0270 J, dated June 2, 2009 of the National Flood Insurance Program Map, Flood Insurance Rate Map of Collin County, Texas, Federal Emergency Management Agency, Federal Insurance Administration.

The surveyor did not abstract the surveyed property. This survey was performed without the benefit of a current title abstract.


> TOPOGRAPHIC SURVEY PROPOSED FAIRVIEW PARKWAY NORTH CITY OF FAIRVIEW, COLLIN COUNTY, TEXAS





Dallas, Texas 75251 DAB 1" = 100'


061182003

OCT. 2015









BENCH MARK LIST

BM#1 TXDOT CONTROL POINT NO. E0430313 BEING A 2-INCH ALUMINUM DISK STAMPED "TXDOT DALLAS GPS E0430313" FOUND IN CONCRETE, ±51 FEET WEST OF STATE HIGHWAY 5 AT FANNIN

ELEV=661.43

BM#2 TXDOT CONTROL POINT NO. E0430261 BEING A 4-INCH ALUMINUM DISK FOUND IN THE GRASS ±54 FEET NORTH FROM NORTHEAST CORNER OF BIBLE CHURCH SIGN, ±73 FEET SOUTHEAST FROM TELEPHONE PEDESTAL, ±90.5 FEET SOUTH FROM CR 377/1375 SIGN AND ±241 FEET NORTH FROM THE CENTER OF COUNTY ROAD

BM#3 SQUARE CUT WITH "X" CUT SET ON NORTHEAST CORNER OF CONCRETE HEADWALL LOCATED ±13 FEET WEST OF GREENVILLE DRIVE AND ±1290 FEET NORTH OF STACY ROAD. ELEV=644.21

BM#4 BENCH TIE NAIL SET IN NORTH SIDE OF POWER POLE LOCATED ±16 FEET WEST OF GREENVILLE DRIVE AND ±54 FEET NORTH OF STACY ROAD.

ELEV=673.51

BM#5 SQUARE CUT ON NORTHEAST CORNER OF CURB INLET ON THE NORTH SIDE OF FRISCO ROAD, ±430 FEET WEST OF THE INTERSECTION OF FRISCO ROAD AND GREENVILLE DRIVE, ±755 FEET EAST OF INTERSECTION OF FRISCO ROAD AND MEDICAL CENTER DRIVE.

ELEV=632.28

BM#6 SQUARE CUT ON BACK OF CURB INLET ON THE SOUTHEAST SIDE OF CENTRAL EXPRESSWAY, ±75 FEET NORTHEAST OF THE INTERSECTION OF CENTRAL EXPRESSWAY AND FRISCO ROAD. ELEV=660.64

BM#7 SQUARE CUT ON SOUTH CORNER OF CURB INLET ON THE SOUTHEAST SIDE OF FAIRVIEW PARKWAY, ±320 FEET SOUTHWEST FROM THE INTERSECTION OF FAIRVIEW PARKWAY AND RIDGEVIEW DRIVE.

ELEV=642.22

TRACT 2 SLOAN CREEK II, LLC INST, NO. 20080221000205890 O.P.R.C.C.T.

All bearings shown are based on grid north of the Texas Coordinate System of 1983, North Central Zone (4202), North American Datum of 1983. All dimensions shown are ground distances.

The property is shown on Map No. 48085C0270J, Community Panel No. 481069 0270 J, dated June 2, 2009 of the National Flood Insurance Program Map, Flood Insurance Rate Map of Collin County, Texas, Federal Emergency Management Agency, Federal Insurance Administration.

The surveyor did not abstract the surveyed property. This survey was performed without the benefit of a current

TOPOGRAPHIC SURVEY PROPOSED FAIRVIEW PARKWAY NORTH CITY OF FAIRVIEW, COLLIN COUNTY, TEXAS



1" = 100'

3 OF 4

DAB

OCT. 2015 061182003

Copyright © 2015 Kimley-Horn and Associates, Inc.